


Not to scale. The cross section is indicative. Elevations in metres above Ordnance Datum (mAOD) are indicative.

Key / Notes

- Chatburn Limestone Formation
- Previously permitted restoration materials
- Restoration materials
- Indicative groundwater flow direction
- Indicative groundwater table based on interpolation of June 2023 groundwater levels
- Indicative recovered groundwater levels following restoration

Notes:
The line of section is consistent generally with the line of A-A' shown on Figure 1 (drawing reference TAR/SK/09-26/25731).

The restoration profile is indicative and based on drawing reference S137-00058-17 (sheets 1 to 3) provided at Appendix F of report reference TAR/SK/AW/5770/02/WRP.

Rev	Status	Drn	App	Chk	Date
	Final	KR	AH	CJC	30/09/26

Site
SKIPTON ROCK QUARRY

Client
TARMAC
A CRH COMPANY

Title
Schematic hydrogeological cross section through the restored site

Figure 2

Scale
NTS

Drawing Ref
TAR/SK/09-26/25732

Reproduced scale mapping by permission of Ordnance Survey© on behalf of The Controller of His Majesty's Stationery Office. © Crown copyright 2026. All rights reserved. Licence number AC0000851450.

MJCA
Technical advisers on environmental issues
Baddesley Colliery Offices,
Main Road, Baxterley, Atherstone,
Warwickshire, CV9 2LE.
Telephone : 01827 717891
Fax : 01827 718507